

Mines Safety Significant Incident Report No. 169

Suspension component ejected under high pressure during maintenance – fatal accident

Summary of incident

In late 2010, an employee sustained fatal injuries after apparently being struck by a suspension component that was ejected under high pressure during a routine maintenance operation.

Probable causes

This incident is under investigation but it demonstrates the hazard posed to employees where:

- they are required to work with equipment subject to stored energy; and
- there is a potential for the release of stored energy in an uncontrolled manner.

Action required

Regulation 6.24(1) of the Mines Safety and Inspection Regulations 1995 states:

- (1) Where plant is dismantled, an employer must ensure that
 - (a) dismantling is carried out by a competent person; and
 - (b) where available, any relevant information provided by the designer and manufacturer is made available to the competent person.

To avoid a recurrence of this type of incident, managers and employers must establish and confirm safe work practices for employees working with stored energy. These include:

- ensuring maintenance personnel
 - are appropriately trained and competent to carry out the task
 - follow original equipment manufacturer (OEM) service requirements and ensure any stored pressure is released in a controlled manner or is effectively isolated;
- where possible, fitting and maintaining warning labels to plant advising of any serious hazard (Figure 1); and
- maintaining effective communication between work groups and shifts, including detailing the work performed and the status of incomplete procedures.

Simon Ridge

STATE MINING ENGINEER

21 January 2011











Decal warns of (a) crush hazard and (b) requirement to support vehicle and consult OEM manual before maintenance



Warning label specific to stored energy hazards. Decal warns of (a) high-pressure hazard and (b) requirement to release pressure and consult OEM manual before maintenance

Figure 1 Examples of warning labels (photographs courtesy of WesTrac Pty Ltd and Caterpillar)